


Workpiece confirmation on a conveyor shuttle



Previous problems

- Cable breakages from stress.
- Visual confirmation required for places impossible to hardwire.




After improvement

- Eliminated stress points and cable breakage problems.
- Full automation made possible.

Application

The conveyor shuttle motion triggered by confirming loading or unloading of the workpiece. Remote System sends power to proximity switches and transmits their signals.



Construction of devices

