



Work piece confirmation on a conveyor shuttle



Previous problems

- Cable breakages from stress.
- Visual confirmation required for places impossible to hardwire.



After improvement

- Eliminated stress points and cable breakage problems.
- Full automation made possible.

Application

The conveyor shuttle motion triggered by confirming loading or unloading of the work piece. Remote System sends power to proximity switches and transmits their signals.

Loading and confirming work piece

Shuttle conveyor in motion

Unloading work piece

Construction of devices

