


# Workpiece detection on a turntable



### Previous problems

- Cable breakages from stress






### After improvement

- Eliminated stress points, eliminated cable breakage problems.
- Free from limitation of cable movement, no need to return to the home position.

### Application

Machining and loading/unloading are performed continuously by turning the turntable which has two jigs  
 Remote System supplies power to proximity switched and transmits the switing state of the sensor.



### Construction of devices

